



Infrastructure

- 53 Structures
- 3 Turnarounds
- 14 Hydrants
- 4 Draft Hydrants
- 14 Pool Locations
- 1 Beacon Box

Totals are tabulated for designated area

Las Flores



georeferenced document
Color Blind Safe
esri Partner Network



FIRE DEPT
BEACON BOX™
MAPS & INFO

by FlameMapper
patents pending

