









Infrastructure

- 53  Structures
- 3  Turnarounds
- 14  Hydrants
- 4  Draft Hydrants
- 14  Pool Locations
- 1  Beacon Box

Totals are tabulated for designated area

Las Flores



georeferenced document



Color Blind Safe



FIRE DEPT
BEACON
 BOX™
 MAPS & INFO

by FlameMapper
 patents pending