


Infrastructure

- 107 Structures
- 4 Turnarounds
- 27 Hydrants
- 0 Draft Hydrants
- 34 Pool Locations
- 2 Beacon Box

Totals are tabulated for designated area

Ramirez Canyon (South)



georeferenced document

Color Blind Safe

FIRE DEPT

BEACON BOX™

MAPS & INFO

by FlameMapper
patents pending