



W Winding/ Murphy Way



- Infrastructure**
- 52 Structures
 - 0 Turnarounds
 - 17 Hydrants
 - 0 Draft Hydrants
 - 23 Pool Locations
 - 1 Beacon Box

Totals are tabulated for designated area

FIRE DEPT
BEACON BOX™
MAPS & INFO

georeferenced document

Color Blind Safe

esri Partner Network

by FlameMapper
patents pending

YOU ARE HERE

Pacific Coast Hwy